



## **Oakland Firesafe Council Survey Highlights Challenges That Still Remain with Inspections of Private/Public Properties in Oakland Hills**

For years, the official results of inspections on private properties in Oakland's high fire severity zone reported 95% or higher compliance with defensible space requirements, despite reports from residents that far fewer properties seemed to be compliance. Late in July and in early September of this year, the Oakland Firesafe Council observed a sample of properties within District 1 and District 4 in what had been the Wildfire Prevention Assessment District (WPAD). The survey revealed that there still is a disconnect between the City's defensible space requirements and the reality of compliance on both private and public properties.

This report highlights some of the ongoing issues facing the City of Oakland in inspecting public and private properties to reduce fire risk in the Oakland Hills. The drive-by survey focused on what could be seen from the street, and used the City's and State's Fire Code regulations as the criteria for assessment.

This unofficial sampling revealed that in District 1 (Warren Freeway to Grizzly Peak, Broadway Terrace to Claremont Canyon), one in three private properties and about half of the public properties were out of compliance as of July 31. In District 4, of the properties along Paso Robles, Balboa, Shepherd Canyon Road, Sayre, Saroni, Homeglen, Homewood, Glencourt, Arrowhead, East, West, Southwood, Manzanita, Villanova, and Skyline from Colton and Shepherd Canyon Park between 10 and 15% of the properties were observed as out of compliance with the City's defensible space regulations. It was much higher on the following streets in District 4:

<b>Residential</b>	<b>Percent</b>
1800 Magellan block	23%
1900 Magellan block	24%
2000 Magellan block	27%
2100 Magellan block	36%
2000 Drake Dr block	43%
5800 Snake Rd block	33%
5900 Zinn Dr block	53%

<< some of these percentages are high due to backyards extending down into another street

The District 4 observations were made during the first week of September, 2017.



### Unresolved Inspection Issues

- invasive ivy is widespread and hides a lot of dead debris; Many homes have ivy and other invasive overgrown bushes like cotoneaster and pampas grass that are clearly not cultivated nor is it irrigated landscaping
- Dead grass, thistle, broom, low lying and dead branches on trees and/or on the ground
- Parked cars on narrow streets are a problem
- Intersections are often overgrown corners, not buildable lots
- Tree limbs touch structures or the ground
- Substantial quantities of fire-prone vegetation on many of the public open space properties that have not been effectively maintained this year and often not been maintained for a number of years. The fire-prone invasives are thriving and spreading around both fire-prone trees in North Oakland, and along many roadside areas along streets and in parks and major open space locations.
- Some active homeless encampments on Caltrans properties near the PG&E substation and also west of Tunnel Road on Hwy. 13 near the Oakland/Berkeley line.

While information about the specific properties has been presented to the Fire Prevention Bureau of the Oakland Fire Department for follow up, the Oakland Firesafe Council presents this report to the Public Safety Committee for their consideration of the broader structural issues that result in so many properties still being out of compliance at the start of high fire season.

### Broader Systemic Issues with Inspection Impact Effectiveness and Timeliness

For years, the Oakland Fire Department has been reporting that 95%-99% of the private properties within the City's high fire severity zone comply with the fire code by the end of the fire season. A number of residents in the area questioned how serious the City was about enforcing the fire code, when the reality looked so different from what was reported. While the Fire Department continues to work on strengthening its inspection and enforcement process, even this year--13 years after the formation of the Wildfire Prevention Assessment District and 26 years after the 1991 Oakland Hills Firestorm--there are still far too many properties out of compliance.

If the properties in question were originally passed during the first round of inspections by the station fire crews, then the issue for the city is the **quality of the training and the monitoring of the fire crews who are tasked with the initial inspections**. We do not know if that is the case and hope that the Public Safety Committee will ask OFD to further investigate this so that they can develop additional measures to improve the quality of initial inspections.



On the other hand, if the **majority of these properties were NOT passed initially and were still awaiting the second or third inspections**, this raises an entirely different set of issues:

1. **The need to better educate the public about their responsibilities and to provide incentives** so that they keep their properties maintained and in compliance with the fire code 365 days a year. Given the high numbers of noncompliance—and delays in bringing properties into compliance—too many property owners still do not understand that it is THEIR responsibility to keep their property up to code at all times, whether or not their property is inspected. There needs to be a comprehensive outreach/education plan—beyond the one mailer in the spring—to lay the foundation for changing behavior and increasing defensible space.
2. **Analysis of the barriers to why the follow up inspections are so slow or non existent.** We believe there are several challenges that contribute to this situation:
  - A. **The ongoing shortage of qualified, experienced Vegetation Management inspection staff due to VM inspectors leaving for higher paying positions** within OFD or elsewhere. This year the Vegetation Management Unit had 7 people vacate the 3 full time and 1 part time positions between January and September. Without sufficient staff, the fire inspectors have been hard pressed to keep up with their responsibilities, resulting in delays in contracting, inspections of vacant properties and follow up (3<sup>rd</sup> round) inspections in Districts 1, 6 & 7.
  - B. **Delays in the hiring process** due to massive unfilled positions throughout the City creating a tremendous backlog in Human Resources.
  - C. A need to find an **alternative system to accommodate the ups and downs in filled positions**. It is understood that encouraging employees to progress in their careers is desirable, but there needs to be a system for backfilling these positions as quickly as possible. One option is to dually train all fire inspectors in both building and vegetation management inspection, and then assigning them to one or the other responsibilities as needed. That would require a Classification Study and new job description, possibly eliminating the distinction between Vegetation Management Inspector and Commercial/Fire Code Inspectors so that the positions could be interchangeable.
  - D. Another issue is **the City's due process schedule for holding property owners accountable**. On paper, a noncompliant owner is given 30 days to bring the property into compliance. If still not in compliance after the second inspection, the property owner has another 15 days to do so. After that, the City can elect to clear the property itself and charge the property owner or put a lien on the property. However, with only \$100,000 budgeted in the General Fund for private property clean up, only a handful of properties are managed this way. And liens will only be collected when properties sell. The City needs to look not only at the due process schedule but also at other ways to receive reimbursement for their expenses.



## Recommendations

1. Given these issues, it seems prudent for the City to survey other jurisdictions in the area to see how they organize their vegetation management inspections (within Fire Department, Code Compliance or other), how they manage their inspections and their city-owned property clearance, and how they recover clearance costs when the property owner isn't taking responsibility for clearing the property.
2. Initiate a Classification Study for Vegetation Management Inspectors, and/or revamp the entire Inspection Unit for OFD to make commercial and vegetation management inspectors interchangeable in duties with the same salaries to stem the ongoing turnaround in staffing among Vegetation Management Inspectors.
3. Fill the full time Vegetation Management Inspector positions as quickly as possible—certainly before the start of the New Year so that the unit is trained and ready to roll before the start of the 2018 Fire Season.
4. Develop an alternative system for staffing the Vegetation Management Unit when workload is at its highest.
5. Review the City's due process schedule for holding property owners accountable. Take best practices from other jurisdictions and adapt to Oakland.
6. Develop and Fund an ongoing public education, outreach and incentive program to reinforce property owner's understanding of their responsibilities to maintain defensible space 365 days a year.

We urge members of the Public Safety Committee to ask the Oakland Fire Department and the City Administrator's Office to delve into the specifics of the attached data, and provide a report on what they learned from their further assessment, a report on how other jurisdictions handle these functions, and recommendations on how Oakland can improve its wildfire inspection process and implementation. This information is critical, not only in the short term, but also as the City moves forward with implementing the 10-year Vegetation Management Plan now in development. Public support of another vegetation management initiative is highly dependent on residents' perceptions of how well the city is inspecting properties within the high fire severity zone, as well as how well the city is maintaining its own properties.

The Oakland Firesafe Council is a non-profit community based organization focused on education and outreach to reduce the risk of wildfires in Oakland. Its members are former members of the WPAD advisory committee and leaders of the Oakland Wildland Stewards (OWLS), volunteers who help maintain many of Oakland's parks and open spaces in the fire prone hills.

September 23, 2017



	Property Owner		Approx. Address or Location	
1	Caltrans		Hwy. 24 interchange area	
2	Caltrans		Old connector road by L. Temescal	
3	Caltrans		Broadway, s. of interchange	
4	Caltrans		Broadway , w. of Sport Field	
5	Caltrans		Btwn 24 & Broadway, w. of overpass	
6	Caltrans		e. of Sp. Field on hillside	
7	Caltrans		s., e., & w. of Tunnel from 24 onramp	
8	Caltrans		e. of Tunnel entry on hillside	
9	Caltrans		n.e. of Tunnel, e. of Parkwoods	
10	Caltrans		w. of bridge, n. of 24, s. of Caldecott	
11	Caltrans		w. of Gateway Garden, n. of Tunnel Rd.	
12	Caltrans		n. of 24 offramp leading to 13 north	
13	Caltrans		n. of interchange along 13 before light	
14	Caltrans		w. of stoplight along 13 nr Memorial G.	
15	Caltrans		w. of 13 opposite Bentley School	
16	Caltrans		traffic islands by stoplight/Hiller Drive	

17	Caltrans		w. of 13 Oakland/Berkeley line	
18	Caltrans		center divider area on Tunnel, Berkeley	
19	Bentley		e. of 13 by sidewalk, Oak/Berk. Line area	
20	Vincent		e. of lower Hiller Drive and stoplight	
21	Kaiser		e. of school bldg. & upper playground	
22	Homes Up. Hiller		w. of 9 homes on Upper Hiller Drive	
23	HHPhase V		Open space n. of Gateway G. & Tunnel rd Grass	
24	City of Oakland s. of Broadway w. of Sports Field fence		s. of Broadway, e.& w. of fence Sp.Field	
25	City of Oakland		s. of Broadway w. Along long slope	
26	City of Oakland w. of parking lot at Sports Field			
27	City of Oakland e. of parking lot at Sports Field			
28	City of Oakland by bathrooms top of parking lot			
29	City of Oakland		s. of bathrooms along Sp. F. service road	
30	City of Oakland		along switchback trail, e of service road	
31	City of Oakland		along service road, w. of service road	
32	City of Oakland		along service road, s. of switchback rd	
33	City of Oakland		e and n.e. of switchback trail, Sp. Field	

34	City of Oakland		s.e. of switchback trail on hillside	
35	City of Oakland		n. of fire trail, e. of service road Sp. Field	
36	City of Oakland		s. of fire trail at end of service road	
37	City of Oakland		Grassy meadow at end of sports field service road	
38	City of Oakland		w. of grassy meadow across Temescal Cr.	
37	City of Oakland		Open Space area/rebuilt hillside area	
38	City of Oakland		Temescal Cr. Channel and outside fence	
39	City of Oakland		w., n., e. of Parkwoods along Tunnel Rd	Brook
40	City of Oakland		n. of Gateway Garden, vacant lot	
41	City of Oakland		e. of Gateway Garden, hillside	
42	City of Oakland		Alvarado Road	
43	City of Oakland		Claremont Canyon	
44	City of Oakland		Panoramic	
45	City of Oakland		Vicente	
46	City of Oakland		Garber Park on Claremont Blvd.	
47	City of Oakland Claremont Hotel		n.&e. of Claremont Hotel	
48	Bay Forest Homes		Nr. Skyline and Bay Forest	
49	Parkwoods	condos	Area surrounding Parkwoods	
50	N. Hill Ct.	homes	Private homes, N. Hill Court	
51	Charing Cross		6678 Charing Cross	Townhome
52	Charing Cross		N. side of Charing Cr. Condoss	



53	Phase I	condos	From Hiller Dr. to end of Spyglass	
54	Phase V		s. of Starview Ct. area to 34 Starview Dr.	
56	Phase V		34-38, 60, 71 and 86-88 Starview Drive	
57	private		Claremont Ave. Many homes along Claremont Ave.	
58	Univ. of CA		Signpost 29 area next to Claremont Ave	
59	Vicente Rd & Place Many homes		Many homes along Vicente Rd.& Pl.	
60	Phase II		Homes n. of Hiller Drive on Treasure H.	
61	Bridge homes Multiple homes along Bridge nr Tunnel R		Homes on Bridge nr. Tunnel Rd/Alvarado	
62	Amito homes/bldg. Homes and Oakland Fire St. on Amito			
63	Grandview homes Homes on Grandview Dr in hill areas			
64	Doris Place Doris Pl nr Grandview			
65	Schooner Hill		Schooner Hill off of Hiller Drive	
66	Phase III		Captains Cover off of Hiller Drive	
67	Phase IV		Clipper Hill above Schooner Hill	
68	Dorothy Dorothy nr Grandview Drive			

69	Gravatt Gravatt homes 200 up to 440					
70	Perth Perth homes nr. Gravatt					
71	Tunnel Rd homes Bentley to Claremont Hotel					
72	Sherwick		Sherwick e./n. of Charing Cross			
73	Bristol Bristol near Sherwick					
74	Buckingham		Buckingham near Bristol			
75	Norfolk		Norfolk near Buckingham			
76	Marlborough		Marlboroug near Norfolk			
77	Alvarado homes Alvarado down to Claremont Ave.		Alvarado down to Cl. Ave.			

Vegt. Mngt. Issues			& # Re Com
Invasive shrubs, junk trees, litter and homeless			
Broom, cotoneaster, multiple homeless encampments			
Broom, pines, roadside hazard vegetation by Hwy 24, by road, hillside			
Invasives next to Broadway and on hillside			
Junk trees surround new trees/shrubs just planted			
Broom, pines and eucalyptus, seasonal grass			
Broom concentrations,, pines, eucs,			
Broom, pines, eucs, grasses all the way to Skyline Blvd.			
Too many pines, broom, next to Parkwoods			
Broom, vast seedbed of broom, pines, eucs, grass			
Fr. & Sp. Broom, grass, pines, eucs, pampas grass			
Many pines, eucs surrounding new native trees/shrubs			
Broom along guard rail adjacent to eucs			
Broom, eucs, grass, on hillside & next to guardrail			
2 or more homeless encampments, broom, eucs, invasives			
Grasses, weeds			

eucs, tall shrubs, homeless encampments down hillside			
Hodge podge broom, trees, shrubs			
Mass of tall trees/shrubs, no separation, def. sp. and f. lad.			
Broom, eucs, euc debris, grasses, euphorbias			
Broom, eucs, poison oak, grasses on hillside above 1st level			
Broom, grasses			
some woody shrubs, vegt. Spacing next to homes			
Large quantities of broom, pampas grass, hillside vegt. 22			
Tall grasses, broom, pampas grass			
Eucs, pampas grass, tall grasses			
Grasses, weeds			
eucs & euc debris			
Large stump by road and smaller stumps and eucs			
Thistles, grasses and some broom			
Branches dumped by tree company			
Thistles, grasses, poison oak			
Eucs, grass, broom, poison oak, cut euc suckers			

Sp. F broom, .Eucs, euc debris& suckers, broom, grasses, poison oak			
Eucs, broom, poison oak, grasses, weeds			
Sp. F. Eucs, broom, weeds, grasses			
Grasses, broom			
Grasses, broom, coyote shrub, vines, weeds			
Grasses, weeds, broom, woody shrubs			
Grasses, broom, weeds, pampas grass			
m, pines, grasses, eucs, limbs over road	39		
Grasses, coyote shrubs, berry vines			
Tall Grasses in middle of hillside			
Weeds, grass, broom by Cl. Ave, trees over Cl. Ave.			
Grass,weeds, trees touchig pwr lines & over Cl. Ave.			
Grass, weeds, littering trees n.&e. of Claremont Hotel			
Trees/shrubs too close to homes, lack of def. space			
Too many pines n., e., w. of homes			
Trees touching, overhanging homes, decks			
Trees too close close & tall grass on hillside to s.&e.			
Trees touching home and close to home			

Trees cl. To homes, touching, some dead on slope			
Tall grass s. of homes on large hillside			
<b>Tree spacing, trees close to homes or touching</b>			
Trees touching or too close to homes/roofs, Broom, thistles, grasses both sides Cl. Ave.			
Broom, thistles, grasses			
Trees & other vegt. Too close or touching homes			
Tree & shrub proximity to homes, very close			
Trees close or overhanging some homes/roofs			
Trees too close to some homes & Fire Station!			
Many homes with trees touching, overhang & close			
1 & 6 Doris Pl trees overhanging or nearly touching			
Some homes trees too close, touching/under eaves			
Some homes trees too close or under eaves			
Some homes with tree touching			
Some homes with trees touching or overhanging			

Many homes with trees close, overhanging			
Trees too close, broom, pampas grass in area			
Trees, heavy vegt., needs to be fire break area			
Some homes trees overhang, too close to homes			
Trees too close, some grasses by road			
Many homes trees too close/overhang, touching			
Trees touching, overhanging			
Many trees overhanging homes, broom cl. To Grizzly P			
Some homes trees overhang, too close to homes			

iments











<b>CRITERIA USED:</b> from Oakland Municipal Code	1 – The address numbers should be posted on the house VISIBLE FROM THE STREET 2 -- Climbing vines must be removed from trees and structures 3 -- Maintain a 10-foot minimum clearance next to the roadside; more may be required 4 -- Remove all portions of trees within 10 feet of chimney and/or stovepipe outlets IN ALL DIRECTIONS.
	Property Owner / City Blocks
1	Snake Rd residential downslope yards & vacant lots -- roadside
2	5800 Block Snake Rd
3	PG&E ? 5800 block Snake Rd
4	2000 block Magellan
5	2000 block Magellan
6	2000 block Magellan
7	2000 block Magellan
8	2100 block Magellan
9	2100 block Magellan
10	2100 block Magellan
11	
12	1900 block Magellan
13	1900 block Magellan
14	1900 block Magellan
15	1800 block Magellan
16	1800 block Magellan
17	City of Oakland (?)
18	Gaspar
19	2000 block Drake
20	2000 block Drake
21	2000 block Drake
22	5900 block Zinn Dr
23	5900 block Zinn Dr
24	5900 block Zinn Dr

25	5900 block Zinn Dr
26	5900 block Zinn Dr
27	5900 block Zinn Dr
28	5900 block Zinn Dr
29	5900 block Zinn Dr
30	5900 block Zinn Dr
31	City of Oakland
32	6000 Zinn at Drake intersection
33	6000 block Zinn Dr (Drake Lane backyards abut Zinn)
34	6000 block Zinn Dr (Drake Lane backyards abut Zinn)
35	6000 block Zinn Dr
36	1800 - 1900 blocks Magellan Rd
37	2100 block Magellan
38	City of Oakland
37	City of Oakland - Mountain Blvd, east border
38	City of Oakland - pedestrian stairway
39	City of Oakland (?)
40	City of Oakland (?)
41	City of Oakland (?)
42	City of Oakland (?)
43	CalTrans - hiway 13 overcrossing
44	CalTrans ? & City of Oakland (?) - parallel to Hiway 13
45	CalTrans? & City of Oakland (?)
46	El Patio block
47	10 El Patio
48	6400 - 6500 block Girvin Rd

49	
	<b>Survey Done 9/11 by Barbara Goldenberg &amp; Nick Vigilante</b>
1	6800 Block - Paso Robles Dr
2	Eastwood Ct
3	Corner Saroni & Paso Robles
4	6700 - 6800 Block Saroni
5	
6	6900 block Saroni
7	corner Homewood & Saroni
8	Azalea Lane
9	
10	
11	7100 block Saroni
12	
13	Corner Gunn & Saroni
14	Corner Sayre & Saroni
15	Across from 7020 and 7026 Sayre
16	6900 - 7000 block Sayre
17	
18	7265 Saroni
19	7200 block Woodrow
20	
21	
22	Corner Woodrow & Las Flores
23	Eastwood Ct
24	
25	Arrowhead
30	2100 block Arrowhead
32	
33	East Wood Circle
34	1900 and 2000 blocks Arrowhead
35	

36	1000 & 1100 Blocks Glencourt
37	
38	
39	Holmglen
40	
41	Homewood
42	Corner Ridgewood Dr & Homewood
43	Homewood
44	
45	
46	Corner Arrowhead & Colton
47	Arrowhead
48	Manzanita
49	
50	Villanove Dr
51	
52	Skyline
53	
54	
55	
56	Skyline - Shep. Canyon Rd to Park entrance
57	Pine Hills Rd , Pine Hills Lane, One Hills Ct
58	Shep. Cyn. Rd at Paso Robles
59	
60	Balboa
61	
62	
63	Paso Robles
64	Asilomar Circle



**General Comments:**

- no sidewalks = veg often extends into street\*
- invasive ivy extremely common everywhere
- hills = many homes' back or side yards extend to one street **but** the front yard/street address is on another street
- house address #s are often very small on mailbox &/or are obscured by veg, &/or have no-contrast (cannot be seen)

**\*unless noted as a sideyard or backyard, all VegMgmt Issues are issues found at immediate roadside or encroaching into road**

**Approx. Addresses or Locations**

uphill easterly side of blocks 5900 - 6400 Snake Rd

side & backyards 5830 - 5814 - 5820 Snake Rd uphill east

across from 5820 Snake - downhill westerly Snake Rd

2000 Magellan - se roadside corner of Magellan at Snake Rd

backyards of 2001 2009 2017 Magellan border Snake Rd

between 2073 & 2115 Magellan

sideyard 2021 Magellan

2126 Magellan

2153 Magellan

between 2159 & 2167 Magellan

between 1930 - 1948 Magellan

1931 Magellan

1973 Magellan backyard onto Cortereal Ave

between 1878 & 1866 Magellan Rd

1822 Magellan

intersection of 2150 Drake at Magellan

blocks 1800 - 1900 Gaspar

intersection of Zinn at Rincon

2085 Drake (?)

2045 Drake

5981 Zinn

across street from 5981 Zinn Dr

5970 Zinn Dr

5935 Zinn Dr
5927 Zinn Dr
lot betw 5915 & 5905 Zinn Dr
side & backyard 5914 Zinn Dr extend onto 5900 Snake
side & backyard 5914 Zinn Dr extend onto 5900 Snake
side & backyard 5914 Zinn Dr extend onto 5900 Snake
Zinn Dr Fire Trail entry beyond 6060 Zinn
at Drake & Zinn bet 2050 Drake & 6000 Zinn
backyard of Drake Lane home across street from 6010 Zinn
below backyards of Drake Lane homes across from 6050 - 6060 Zinn
on street across from 6030 Zinn Dr
1840, 1866, 1878, 1923, 1948 Magellan properties - roadside
2149-2153 Magellan properties - backyards abutting Montclair RR Trail
Montclair RR Trail behind 2100 block Magellan
across from Park Blvd Hiway 13 exit - betw "Montclair" sign at retaining wall to Scout f
between 1840-1844 Magellan Rd
block 5600 Scout Rd both sides of road - west of Mountain Blvd
Mountain Blvd west border betw La Salle & Park Blvd
block 2600 Mountain Blvd east border, flanking Sequoia Lodge entry
Moraga Ave west border betw Thornhill & La Salle
Park Blvd & Trafalgar Hiway 13 at southbound exit
blocks 2500 - 2600 Mountain Blvd - westerly border
Moraga Rd underpass to Thornhill intersection
block 10-63 El Patio - west side parallel to Hiway 13
Mountain Blvd easterly side of 10 El Patio backyard

6800 & 6874
2 Eastwood Ct. (known rental ppty)
6726 - Oak tree limb leaning on wooden fence
Between 6852 & 6856. Ivy Far up Monterey Pines
6915 - branches brushing against house (Big Redwood)
6981 Saroni and 7011 Homewood
18 Azalea
10 Azalea Lane
1 Azalea -
7101 Saroni
Behind 7196 Saroni downslope toward ephemeral creek (Saroni Creek?)
Uphill side
7296 Sayre
May be bottom of a thru lot?
7000 Sayre
6950 & 6962
across from 7200
Several vacant or bottom of thru lots across from 7230
7280 Woodrow
Across from entrance to Las Flores
Parked vehicles obstruct thru traffic (esp. emergency vehicles)
40 & 48 Eastwood
Left of 2275
2148 - adjacent to PG&E HV Power lines
Across from 2140
7 E Wood Cir
Uphill from 2000 - vacant lot
Adjacent to 1920 Arrowhead - vacant lot on right side

1144 -
1122
1035
Across from 55 Holmglen (along a fence of house on Homewood - # unknown
55 Holmglen
7043 & 7046 & Power Pole 110379290
Steep downhill slope - unclear whose property or address
Across from 7084 (back of a lot on Ridgewood?)
Across from 7210 Homewood
across from 7250 Homewood - 200 to 300 feet or more
Surrounding ATT supply box
Across from 1677
The Hills Tennis Club
2620
Left of #1
Whole est side of Villanova overlooks canyon into Contra Costa County
across from 7407 near OFD Station 6
7555
Adjacent to 7555
Adjacent to 7716
Roadside
Corner PH Ct & Dr.
Near the walking trail toward Saroni
Uphill a bit on Paso Robles - may be downslope of a home on Woodrow
Across from 6018 - extremely narrow due to landslide and Jersey barriers
Adjacent to 5917 - to the left
5754
Above corner at Woodrow - vacant lot?
Across from EMBUD Reservoir

*Vegt. Mngt. Issues (at roadside unless noted otherwise)	
dry grass, weeds, euc debris, ivy	
broom, ivy, veg & euc debris, pine needles, weeds	
dead pines, dense pine debris	
dry grass, weeds, ivy, ivy in trees, cotoneaster, juniper, many old Monterey pines, dead branches, veg debris	
dry veg, pine needles, ivy, ivy in trees, blackberries, branches overgrowth extend into roadway	
broom, grass, weeds, dry veg debris	
dry bushes, trees, ivy into road	
dry bushes, ivy into road	
dense bamboo thicket, juniper & ivy into road	
dry veg debris, dense trees, ivy up trees	
overhanging pepper tree & redwood tree, low branches dry grasses, rosemary into roadside	
cedar branches too close to chimney	
dense ivy, dry grass, low tree branches at road	
dead ivy, dry veg debris, climbing ivy, juniper at road	
missing house #, dense carpet pine needles down to road	
dense broom, dry grass, weeds, ivy into trees, cotoneaster	
pampas grass, ivy, overhanging euc branches, broom	
ivy into road, ivy into bushes	
no house #	
dense juniper at street, dry debris, weeds	
unreadable house #, juniper into road	
no house #, low pine branches into road	
Dense ivy into road and up into trees	

dense rosemary draped into dry grass & veg debris onto road	
dry veg debris & dry ivy into road	
dry grass & weeds, pine tree, pine needles, cotoneaster	
Dry veg debris, dense ivy into road & up into trees, pine needle debris, branches overhanging road	
Dry veg debris, dense ivy into road & up into trees, pine needle debris, branches overhanging road	
Dry veg debris, dense ivy into road & up into trees, pine needle debris, branches overhanging road	
piles of dry leaves, grasses, dense stands of broom, euc debris, ivy in trees	
dense pine debris, low pine tree branches, ivy up into tree & down to dry grasses & rosemary at street	
dense stand of broom up to wood deck	
ivy encompass entire yard to house from yard climbing up trees & down to dry grass, rosemary at street	
broom, dry, grass, & rosemary	
street # visibility or missing, pampas grass, ivy, ivy up into trees, dead trees, juniper, tree clearance, dry veg debris	
dense brush & trees, ivy, Monterey pines, debris, dead branches	
dense brush & trees, ivy, Monterey pines, debris, dead branches	
dry grasses, dense stand of black acacia trees	
dry grasses & weeds, massive stand of dry broom	
low trees, stands of broom, dry grass	
overhanging ivy, dry grasses, weeds, overhanging branches	
dry grasses, weeds, dense trees	
ivy, dry grasses, weeds, overhanging trees	
massive amount of broom & fennel, dry weeds	
dense overgrowth of ivy, trees, bushes, dry grasses & weeds	
dense brush, ivy, broom, grass, weeds, debris	
dense veg, ivy broom, euc debris, grass weeds veg debris	
dense blackberries, grasses into road	
tree branches touching houses, branches within 10ft of chimney, wood stored under front deck, tree clearance, dry veg debris, dense euc branches	

Dry tall grass; big juniper close to house	
French broom, dry twiggy branches	
Tall Privacy Hedge touching Deck and house	
Monterey Pine in PGE Transmission Line - tree not marked	
Pine leaning toward HV Transmission Line	
Ivy growing up tree	
Large dead Pride of Madeira (Echium) leaning of wood fence	
Dead trees and fallen branches within 100 feet of 2 homes	
Dead bushes, dry high grass, lots of broom -	
Dead and live Vegetation touching house & fence	
Dead grass into low down Monterey Cypress	
Dead Thistles under low hanging vegetation	
Broom and coyote brush around mailbox and under branches of bigger trees	
Jungle of vegetation	
Grass & large Pampas within 10 feet of 7211	
Dead & dying Eucs and Euc. Debris (downslope from PG&E HV Power Lines	
Tall bamboo & broom against wooden fence	
Broom, Dead branches, Pampas grass (may be city lot, or roadway	
Heavy juniper intertwined with blackberry close to houses and wood decks	
Oleander growing into street	
Fire ladder of high dead grasses, broom, to monterey Pine to house	
Ephemeral Creed clogged with dead limbs, broom, downed tree, dead limbs piled up	
Tree touching house	
Broom, tall dead grass, decrepit tree house decomposing in oak tree, with lots of decaying lumber leaning on tree	
Dry thistle, broom next to large juniper & rosemary at 1920	

Tall broom along rear near house; dry grass in front	
dead branches overhanging street	
Lots of dead overhanging branches	
Fire ladder of broom and dry grass to ivy growing into Bay trees	
Ivy covering tree 30+ feet high, into electric and phone supply lines	
Toll overgrown juniper and curlyJuniper next to houses & Ivy growing up trees next to Power Pole	
Ivy covering many trees	
Thicket of thistle and dead vegetation - leading to houses above	
Dry grass & thistles on upslope leading to houses above	
dry grass, dead branches in ephemeral creek, and PG&E debris from branches pruned and taken down trees	
Tangle of dead branches piled around ATT facility	
Tangle of dead branches	
Big dead Juniper adjacent to building entrance &	
Dead branches overhanging dry grasses	
Fire ladder: Thicket of dry hemlock & grasses into bay trees -	
Heavy vegetation - risk if fire starts downhill	
Dry Thistle, dead branches below house; Etc sprouts	
Gutters crammed with dead leaves	
Tall dry thistles	
Huge tall dry thistle patch	
Lots of broom, and branches overhanging road -	
Bushes completely obscure street signs	
Downed Trees, branches with leaves attached	
Dumped pile of branches	
dead/ dry Pride of Madeira (Echium)	
High dry grass & thistle upslope to a yellow outbuilding/cabin	
Low overhanging dead tree branches -	
Uprooted tree stump (15 feet or more) just hanging toward road from above steep hill.	
Unable to proceed due to cars parked on both sides of road	





[illegible]

[illegible]



2000 Magellan @ Snake



Girvin Rd



	Property Owner		Approx. Address or Location		Vegt. Mngt. Issues	& # Re Comments
1	Caltrans		Hwy. 24 interchange area		Invasive shrubs, junk trees, litter and homeless	
2	Caltrans		Old connector road by L. Temescal		Broom, cotoneaster, multiple homeless encampments	
3	Caltrans		Broadway, s. of interchange		Broom, pines, roadside hazard vegetation by Hwy 24, by road, hillside	
4	Caltrans		Broadway , w. of Sport Field		Invasives next to Broadway and on hillside	
5	Caltrans		Btwn 24 & Broadway, w. of overpass		Junk trees surround new trees/shrubs just planted	
6	Caltrans		e. of Sp. Field on hillside		Broom, pines and eucalyptus, seasonal grass	
7	Caltrans		s., e., & w. of Tunnel from 24 onramp		Broom concentrations,, pines, eucs,	
8	Caltrans		e. of Tunnel entry on hillside		Broom, pines, eucs, grasses all the way to Skyline Blvd.	
9	Caltrans		n.e. of Tunnel, e. of Parkwoods		Too many pines, broom, next to Parkwoods	
10	Caltrans		w. of bridge, n. of 24, s. of Caldecott		Broom, vast seedbed of broom, pines, eucs, grass	
11	Caltrans		w. of Gateway Garden, n. of Tunnel Rd.		Fr. & Sp. Broom, grass, pines, eucs, pampas grass	
12	Caltrans		n. of 24 offramp leading to 13 north		Many pines, eucs surrounding new native trees/shrubs	
13	Caltrans		n. of interchange along 13 before light		Broom along guard rail adjacent to eucs	
14	Caltrans		w. of stoplight along 13 nr Memorial G.		Broom, eucs, grass, on hillside & next to guardrail	

15	Caltrans		w. of 13 opposite Bentley School		2 or more homeless encampments, broom, eucs, invasives	
16	Caltrans		traffic islands by stoplight/Hiller Drive		Grasses, weeds	
17	Caltrans		w. of 13 Oakland/Berkeley line		eucs, tall shrubs, homeless encampments down hillside	
18	Caltrans		center divider area on Tunnel, Berkeley		Hodge podge broom, trees, shrubs	
19	Bentley		e. of 13 by sidewalk, Oak/Berk. Line area		Mass of tall trees/shrubs, no separation, def. sp. and f. lad.	
20	Vincent		e. of lower Hiller Drive and stoplight		Broom, eucs, euc debris, grasses, euphorbias	
21	Kaiser		e. of school bldg. & upper playground		Broom, eucs, poison oak, grasses on hillside above 1st level	
22	Homes Up. Hiller		w. of 9 homes on Upper Hiller Drive		Broom, grasses	
23	HHPhase V		Open space n. of Gateway G. & Tunnel rd	Grass	some woody shrubs, vegt. Spacing next to homes	
24	City of Oakland s. of Broadway w. of Sports Field fence		s. of Broadway, e.& w. of fence	Sp.Field	Large quantities of broom, pampas grass, hillside vegt. 22	
25	City of Oakland		s. of Broadway w.	Along long slope	Tall grasses, broom, pampas grass	
26	City of Oakland w. of parking lot at Sports Field				Eucs, pampas grass, tall grasses	
27	City of Oakland e. of parking lot at Sports Field				Grasses, weeds	
28	City of Oakland by bathrooms top of parking lot				eucs & euc debris	
29	City of Oakland		s. of bathrooms along Sp. F. service road		Large stump by road and smaller stumps and eucs	
30	City of Oakland		along switchback trail, e of service road		Thistles, grasses and some broom	

31	City of Oakland		along service road, w. of service road	Branches dumped by tree company	
32	City of Oakland		along service road, s. of switchback rd	Thistles, grasses, poison oak	
33	City of Oakland		e and n.e. of switchback trail, Sp. Field	Eucs, grass, broom, poison oak, cut euc suckers	
34	City of Oakland		s.e. of switchback trail on hillside	Sp. F broom, .Eucs, euc debris& suckers, broom, grasses, poison oak	
35	City of Oakland		n. of fire trail, e. of service road Sp. Field	Eucs, broom, poison oak, grasses, weeds	
36	City of Oakland		s. of fire trail at end of service road	Sp. F. Eucs, broom, weeds, grasses	
37	City of Oakland		Grassy meadow at end of sports field service rd	Grasses, broom	
38	City of Oakland		w. of grassy meadow across Temescal Cr.	Grasses, broom, coyote shrub, vines, weeds	
37	City of Oakland		Open Space area/rebuilt hillside area	Grasses, weeds, broom, woody shrubs	
38	City of Oakland		Temescal Cr. Channel and outside fence	Grasses, broom, weeds, pampas grass	
39	City of Oakland		w., n., e. of Parkwoods along Tunnel Rd	Broom, pines, grasses, eucs, limbs over road	
40	City of Oakland		n. of Gateway Garden, vacant lot	Grasses, coyote shrubs, berry vines	
41	City of Oakland		e. of Gateway Garden, hillside	Tall Grasses in middle of hillside	
42	City of Oakland		Alvarado Road		
43	City of Oakland		Claremont Canyon	Weeds, grass, broom by Cl. Ave, trees over Cl. Ave.	
44	City of Oakland		Panoramic		
45	City of Oakland		Vicente		
46	City of Oakland		Garber Park on Claremont Blvd.	Grass,weeds, trees touchig pwr lines & over Cl. Ave.	
47	City of Oakland Claremont Hotel		n.&e. of Claremont Hotel	Grass, weeds, littering trees n.&e. of Claremont Hotel	
48	Bay Forest Homes		Nr. Skyline and Bay Forest	Trees/shrubs too close to homes, lack of def. space	



49	Parkwoods	condos	Area surrounding Parkwoods			Too many pines n., e., w. of homes	
50	N. Hill Ct.	homes	Private homes, N. Hill Court			Trees touching, overhanging homes, decks	
51	Charing Cross		6678 Charing Cross	Townhome		Trees too close close & tall grass on hillside to s.&e.	
52	Charing Cross		N. side of Charing Cr. Condoss			Trees touching home and close to home	
53	Phase I	condos	From Hiller Dr. to end of Spyglass			Trees cl. To homes, touching, some dead on slope	
54	Phase V		s. of Starview Ct. area to 34 Starview Dr.			Tall grass s. of homes on large hillside	
56	Phase V		34-38, 60, 71 and 86-88 Starview Drive			<b>Tree spacing, trees close to homes or touching</b>	
57	private		Claremont Ave. Many homes along Claremont Ave.			Trees touching or too close to homes/roofs, Broom, thistles, grasses both sides Cl.	
58	Univ. of CA		Signpost 29 area next to Claremont Ave			Broom, thistles, grasses	
59	Vicente Rd & Place Many homes		Many homes along Vicente Rd.& Pl.			Trees & other vegt. Too close or touching homes	
60	Phase II		Homes n. of Hiller Drive on Treasure H.			Tree & shrub proximity to homes, very close	
61	Bridge homes Multiple homes along Bridge nr Tunnel R		Homes on Bridge nr. Tunnel Rd/Alvarado			Trees close or overhanging some homes/roofs	
62	Amito homes/bldg. Homes and Oakland Fire St. on Amito					Trees too close to some homes & Fire Station!	
63	Grandview homes Homes on Grandview Dr in hill areas					Many homes with trees touching, overhang & close	

64	Doris Place Doris Pl nr Grandview					1 & 6 Doris Pl trees overhanging or nearly touching	
65	Schooner Hill		Schooner Hill off of Hiller Drive			Some homes trees too close, touching/under eaves	
66	Phase III		Captains Cover off of Hiller Drive			Some homes trees too close or under eaves	
67	Phase IV		Clipper Hill above Schooner Hill			Some homes with tree touching	
68	Dorothy Dorothy nr Grandview Drive					Some homes with trees touching or overhanging	
69	Gravatt Gravatt homes 200 up to 440					Many homes with trees close, overhanging	
70	Perth Perth homes nr. Gravatt					Trees too close, broom, pampas grass in area	
71	Tunnel Rd homes Bentley to Claremont Hotel					Trees, heavy vegt., needs to be fire break area	
72	Sherwick		Sherwick e./n. of Charing Cross			Some homes trees overhang, too close to homes	
73	Bristol Bristol near Sherwick					Trees too close, some grasses by road	
74	Buckingham		Buckingham near Bristol			Many homes trees to close/overhang, touching	
75	Norfolk		Norfolk near Buckingham			Trees touching, overhanging	
76	Marlborough		Marlborough near Norfolk			Many trees overhanging homes, broom cl. To Grizzly P	
77	Alvarado homes Alvarado down to Claremont Ave.		Alvarado down to Cl. Ave.			Some homes trees overhang, too close to homes	

CRITERIA USED: from Oakland Municipal Code	1 – The address numbers should be posted on the house VISIBLE FROM THE STREET	<b>General Comments:</b> - no sidewalks = veg often extends into street* - invasive ivy extremely common everywhere - hills = many homes' back or side yards extend to one street <b>but</b> the front yard/street address is on another street - house address #s are often very small on mailbox &/or are obscured by veg, &/or have no-contrast (cannot be seen)  <b>*unless noted as a sideyard or backyard, all VegMgmt Issues are issues found at immediate roadside or encroaching into road</b>		
	2 -- Climbing vines must be removed from trees and structures			
	3 -- Maintain a 10-foot minimum clearance next to the roadside; more may be required			
	4 -- Remove all portions of trees within 10 feet of chimney and/or stovepipe outlets IN ALL DIRECTIONS.			
	Property Owner / City Blocks	Approx. Addresses or Locations	*Vegt. Mngt. Issues (at roadside unless noted otherwise)	& # Re Comments
	Snake Rd residential downslope yards			
	1 & vacant lots -- roadside	uphill easterly side of blocks 5900 - 6400 Snake Rd	dry grass, weeds, euc debris, ivy	
	2 5800 Block Snake Rd	side & backyards 5830 - 5814 - 5820 Snake Rd uphill east	needles, weeds	
	3 PG&E ? 5800 block Snake Rd	across from 5820 Snake - downhill westerly Snake Rd	dead pines, dense pine debris	
	4 2000 block Magellan	2000 Magellan - se roadside corner of Magellan at Snake Rd	dry grass, weeds, ivy, ivy in trees, cotoneaster, juniper, many old Monterey pines, dead branches, veg debris	
	5 2000 block Magellan	backyards of 2001 2009 2017 Magellan border Snake Rd	blackberries, branches overgrowth extend into roadway	
	6 2000 block Magellan	between 2073 & 2115 Magellan	broom, grass, weeds, dry veg debris	
	7 2000 block Magellan	sideyard 2021 Magellan	dry bushes, trees, ivy into road	
	8 2100 block Magellan	2126 Magellan	dry bushes, ivy into road	
	9 2100 block Magellan	2153 Magellan	road	
	10 2100 block Magellan	between 2159 & 2167 Magellan	dry veg debris, dense trees, ivy up trees	
	11			
	12 1900 block Magellan	between 1930 - 1948 Magellan	tree, low branches dry grasses, rosemary into roadside	
	13 1900 block Magellan	1931 Magellan	cedar branches too close to chimney	
	14 1900 block Magellan	1973 Magellan backyard onto Cortereal Ave	road	
	15 1800 block Magellan	between 1878 & 1866 Magellan Rd	juniper at road	
	16 1800 block Magellan	1822 Magellan	missing house #, dense carpet pine needles down to road	
	17 City of Oakland (?)	intersection of 2150 Drake at Magellan	dense broom, dry grass, weeds, ivy into trees, cotoneaster	
	18 Gaspar	blocks 1800 - 1900 Gaspar	branches, broom	
	19 2000 block Drake	intersection of Zinn at Rincon	ivy into road, ivy into bushes	
	20 2000 block Drake	2085 Drake (?)	no house #	

21	2000 block Drake	2045 Drake	weeds	
22	5900 block Zinn Dr	5981 Zinn	unreadable house #, juniper into road	
23	5900 block Zinn Dr	across street from 5981 Zinn Dr	no house #, low pine branches into road	
24	5900 block Zinn Dr	5970 Zinn Dr	Dense ivy into road and up into trees	
			dense rosemary draped into dry grass & veg debris onto road	
25	5900 block Zinn Dr	5935 Zinn Dr		
26	5900 block Zinn Dr	5927 Zinn Dr	dry veg debris & dry ivy into road	
			dry grass & weeds, pine tree, pine needles, cotoneaster	
27	5900 block Zinn Dr	lot betw 5915 & 5905 Zinn Dr		
			into trees, pine needle debris, branches overhanging road	
28	5900 block Zinn Dr	side & backyard 5914 Zinn Dr extend onto 5900 Snake		
			into trees, pine needle debris, branches overhanging road	
29	5900 block Zinn Dr	side & backyard 5914 Zinn Dr extend onto 5900 Snake		
			into trees, pine needle debris, branches overhanging road	
30	5900 block Zinn Dr	side & backyard 5914 Zinn Dr extend onto 5900 Snake		
			into trees, pine needle debris, branches overhanging road	
31	City of Oakland	Zinn Dr Fire Trail entry beyond 6060 Zinn	piles of dry leaves, grasses, dense stands of broom, euc debris, ivy in trees	
			branches, ivy up into tree & down to dry grasses & rosemary at street	
32	6000 Zinn at Drake intersection	at Drake & Zinn bet 2050 Drake & 6000 Zinn		
33	backyards abut Zinn)	backyard of Drake Lane home across street from 6010 Zinn	dense stand of broom up to wood deck	
			ivy encompass entire yard to house from yard climbing up trees & down to dry grass, rosemary at street	
34	6000 block Zinn Dr (Drake Lane backyards abut Zinn)	below backyards of Drake Lane homes across from 6050 - 60		
35	6000 block Zinn Dr	on street across from 6030 Zinn Dr	broom, dry, grass, & rosemary	
			street # visibility or missing, pampas grass, ivy, ivy up into trees, dead trees, juniper, tree clearance, dry veg debris	
36	1800 - 1900 blocks Magellan Rd	1840, 1866, 1878, 1923, 1948 Magellan properties - roadside		
			dense brush & trees, ivy, Monterey pines, debris, dead branches	
37	2100 block Magellan	2149-2153 Magellan properties - backyards abutting Montclair		
			dense brush & trees, ivy, Monterey pines, debris, dead branches	
38	City of Oakland	Montclair RR Trail behind 2100 block Magellan		
37	border	across from Park Blvd Hiway 13 exit - betw "Montclair" sign at	trees	
38	City of Oakland - pedestrian stairway	between 1840-1844 Magellan Rd	dry broom	
39	City of Oakland (?)	block 5600 Scout Rd both sides of road - west of Mountain Bl	low trees, stands of broom, dry grass	
			overhanging ivy, dry grasses, weeds, overhanging branches	
40	City of Oakland (?)	Mountain Blvd west border betw La Salle & Park Blvd		
41	City of Oakland (?)	block 2600 Mountain Blvd east border, flanking Sequoia Lodge	dry grasses, weeds, dense trees	
42	City of Oakland (?)	Moraga Ave west border betw Thornhill & La Salle	trees	
43	CalTrans - hiway 13 overcrossing	Park Blvd & Trafalgar Hiway 13 at southbound exit	weeds	

44	CalTrans ? & City of Oakland (?) - parallel to Hiway 13	blocks 2500 - 2600 Mountain Blvd - westerly border	dense overgrowth of ivy, trees, bushes, dry grasses & weeds	
45	CalTrans? & City of Oakland (?)	Moraga Rd underpass to Thornhill intersection	debris	
46	El Patio block	block 10-63 El Patio - west side parallel to Hiway 13	dense veg, ivy broom, euc debris, grass weeds veg debris	removed from trees and structures
47	10 El Patio	Mountain Blvd easterly side of 10 El Patio backyard	dense blackberries, grasses into road	-- Maintain a 10-foot minimum clearance next to the roadside; more may be required
48	6400 - 6500 block Girvin Rd		within 10ft of chimney, wood stored under front deck, tree clearance, dry veg debris, dense euc branches	– The address numbers should be posted on the house VISIBLE FROM THE STREET. Remove all portions of trees within 10 feet of chimney and/or stovepipe outlets IN ALL DIRECTIONS.
49				
	<b>Goldenberg &amp; Nick Vigilante</b>			
1	6800 Block - Paso Robles Dr	6800 & 6874	Dry tall grass; big juniper close to house	
2	Eastwood Ct	2 Eastwood Ct. (known rental ppty)	French broom, dry twiggy branches	
3	Corner Saroni & Paso Robles			
4	6700 - 6800 Block Saroni	6726 - Oak tree limb leaning on wooden fence		
5		Between 6852 & 6856. Ivy Far up Monterey Pines		
6	6900 block Saroni	6915 - branches brushing against house (Big Redwood)		
7	corner Homewood & Saroni	6981 Saroni and 7011 Homewood	house	
8	Azalea Lane	18 Azalea	tree not marked	
9		10 Azalea Lane	Line	
10		1 Azalea -	Ivy growing up tree	
11	7100 block Saroni	7101 Saroni	Large dead Pride of Madeira (Echium) leaning of wood fence	
12		Behind 7196 Saroni downslope toward ephemeral creek (Sar	100 feet of 2 homes	
13	Corner Gunn & Saroni	Uphill side	broom -	
14	Corner Sayre & Saroni	7296 Sayre	& fence	
15	Across from 7020 and 7026 Sayre	May be bottom of a thru lot?	Cypress	
16	6900 - 7000 block Sayre	7000 Sayre	vegetation	
17		6950 & 6962	Broom and coyote brush around mailbox and under branches of bigger trees	
18	7265 Saroni		Jungle of vegetation	
19	7200 block Woodrow	across from 7200	7211	
20		Several vacant or bottom of thru lots across from 7230	Dead & dying Eucs and Euc. Debris (downslope from PG&E HV Power Lines	
21		7280 Woodrow	fence	

22	Corner Woodrow & Las Flores	Across from entrance to Las Flores	Broom, Dead branches, Pampas grass (may be city lot, or roadway)	
23	Eastwood Ct	Parked vehicles obstruct thru traffic (esp. emergency vehicles)		
24		40 & 48 Eastwood	Heavy juniper intertwined with blackberry close to houses and wood	
25	Arrowhead	Left of 2275	Oleander growing into street	
30	2100 block Arrowhead	2148 - adjacent to PG&E HV Power lines	Fire ladder of high dead grasses, broom, to monterey Pine to house	
32		Across from 2140	Ephemeral Creed clogged with dead limbs, broom, downed tree, dead limbs	
33	East Wood Circle	7 E Wood Cir	Tree touching house	
34	1900 and 2000 blocks Arrowhead	Uphill from 2000 - vacant lot	Broom, tall dead grass, decrepit tree house decomposing in oak tree, with lots	
35		Adjacent to 1920 Arrowhead - vacant lot on right side	Dry thistle, broom next to large juniper & rosemary at 1920	
36	1000 & 1100 Blocks Glencourt	1144 -	grass in front	
37		1122	dead branches overhanging street	
38		1035	Lots of dead overhanging branches	
39	Holmglen	Across from 55 Holmglen (along a fence of house on Homewood)	Fire ladder of broom and dry grass to ivy growing into Bay trees	
40		55 Holmglen	Ivy covering tree 30+ feet high, into electric and phone supply lines	
41	Homewood	7043 & 7046 & Power Pole 110379290	Toll overgrown juniper and curlyJuniper next to houses & Ivy growing up trees	
42	Corner Ridgewood Dr & Homewood	Steep downhill slope - unclear whose property or address	Ivy covering many trees	
43	Homewood	Across from 7084 (back of a lot on Ridgewood?)	Thicket of thistle and dead vegetation - leading to houses above	
44		Across from 7210 Homewood	houses above	
45		across from 7250 Homewood - 200 to 300 feet or more	dry grass, dead branches in ephemeral creek, and PG&E debris from branches	
46	Corner Arrowhead & Colton	Surrounding ATT supply box	ATT facility	
47	Arrowhead	Across from 1677	Tangle of dead branches	
48	Manzanita	The Hills Tennis Club	entrance &	
49		2620	Dead branches overhanging dry grasses	
50	Villanove Dr	Left of #1	Fire ladder: Thicket of dry hemlock & grasses into bay trees -	
51		Whole est side of Villanova overlooks canyon into Contra Costa	downhill	
52	Skyline	across from 7407 near OFD Station 6	Etc sprouts	
53		7555	Gutters crammed with dead leaves	
54		Adjacent to 7555	Tall dry thistles	
55		Adjacent to 7716	Huge tall dry thistle patch	
56	entrance	Roadside	overhanging road -	
57	Ct	Corner PH Ct & Dr.	Bushes completely obscure street signs	
58	Shep. Cyn. Rd at Paso Robles	Near the walking trail toward Saroni	attached	

59		Uphill a bit on Paso Robles - may be downslope of a home on	Dumped pile of branches	
60	Balboa	Across from 6018 - extremely narrow due to landslide and Je	dead/ dry Pride of Madeira (Echium)	
61		Adjacent to 5917 - to the left	High dry grass & thistle upslope to a yellow outbuilding/cabin	
62		5754	Low overhanging dead tree branches -	
63	Paso Robles	Above corner at Woodrow - vacant lot?	Uprooted tree stump (15 feet or more) just hanging toward road from above	
64	Asilomar Circle	Across from EMBUD Reservoir	Unable to proceed due to cars parked on both sides of road	

2000 Magellan @ Snake



Girvin Rd

